

10/607632

cogc

# BLAKELY SOKOLOFF TAYLOR & ZAFMAN

A LIMITED LIABILITY PARTNERSHIP INCLUDING LAW CORPORATIONS

TELEPHONE (408) 720-8300

FACSIMILE (408) 720-8383

BSTZ\_MAIL@BSTZ.COM

WWW.BSTZ.COM

INTELLECTUAL PROPERTY LAW

SILICON VALLEY

1279 OAKMEAD PARKWAY  
SUNNYVALE, CALIFORNIA 94085-4040

OTHER OFFICES

LOS ANGELES, CA  
ORANGE COUNTY/COSTA MESA, CA  
SAN JOSE, CA  
DENVER, CO  
PORTLAND/BEAVERTON, OR  
SEATTLE, WA

July 13, 2005

Commissioner for Patents  
PO Box 1450  
Alexandria, VA 22313-1450


Re: **CERTIFICATE OF CORRECTION**  
U. S. Letters Patent No. 6,909,151  
Issued: June 21, 2005  
For: **NONPLANAR DEVICE WITH STRESS  
INCORPORATION LAYER AND METHOD  
OF FABRICATION**  
Inventor: Hareland, et al.  
Our File No. 42390.P15677

Dear Sir:

Enclosed is the Certificate of Correction (two copies) for the above-referenced patent.  
This request for correction is made under rule 322 of the Rules of Practice and 35 U.S.C.  
Section 254.

Respectfully submitted,

BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN LLP

  
Edwin H. Taylor  
Reg. No. 25,129

Certificate

JUL 29 2005

of Correction

EHT/cgb  
Enclosures

JUL 29 2005

**UNITED STATES PATENT AND TRADEMARK OFFICE**  
**CERTIFICATE OF CORRECTION**

**PATENT NO.** : 6,909,151  
**DATED** : June 21, 2005  
**INVENTOR(S)** : Hareland

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 7, at line 57, delete "100mVN" and insert --100m V/V--.  
In column 7, at line 57, delete "40m VN" and insert --40m V/V--.  
In column 16, at line 28, delete "sidewalk" and insert --sidewalls--.

**MAILING ADDRESS OF SENDER**  
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN  
12400 Wilshire Blvd. 7th floor  
Los Angeles, CA 90025-1026

**PATENT NO.** **6,909,151**

**Certificate of Correction (PTO Form 1050)-Amended**

JUL 29 2005